

Running Fix Process.

Observations:

1. First Bearing of object, time, course and log reading.
2. Second bearing of object, time and log reading.
3. Tide set and drift for the period between observations 1 and 2.

